

AirBag_Tesla_R7F701330

Table of contents

Requiment 3

Read / Erase Errors 3


Clear Crash by Jtag 4

Requiment

1. UHDS
- 2.Jtag
- 3.Jtag sonde v2
- 4.Cable Bench Cnnection (for test module only)
5. Activation AB0073
- 6.Activation JG0050




Read / Erase Errors

For Read / Erase errors on bench connect +12V ,GND and Diagnostc CAN



Clear Crash by Jtag

Tesla R7F701330 Airbag



Remove this Component .
After programming install Back
If you lost it you can solder 100nf
capacitor.

Sonde v2 P 0.33R

Desolder 8 capacitors

