PSA_CMB_P2JO_Visteon

Table of contents

Getting Started

System requirements

1. UHDS Interface
2. PT0020 Activation
3. Cable bench connection

Getting help

Possible options:
1. Read Km
2. Write EEprom